



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

January 19, 2007

Supervisor *[Signature]*

Mine Name: Elite Rock West
Operator Name: Wasatch Mountain Excavating, Inc.

Permit number: M0490050
Inspection Date: May 17, 2006
Time: 11:00 am

Inspector(s): Lynn Kunzler, DOGM
Other Participants: none
Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This was a routine inspection while in the area.

Inspection Summary:

- This site was active. The site appeared to be approaching the 5- acre limit for a small mining operation. The disturbed area was surveyed with the GPS to determine acreage currently disturbed. An area to the northern portion of the disturbance has been regraded and seeded, and a small area to the north east (about 1/4 acre) has been disturbed by dumping soil and tree limbs on it (a later conversation with the operator indicated that this material came from a storm drain cleanout which the operator had been involved in, and felt that he could use it to enhance future reclamation of this site. He gave permission to the City to dump the material at the site).

Conclusions and Recommendations:

- Results of the GPS monitoring showed about 5-1/2 acres of disturbance. However, about 3/4 acre had been regraded and seeded (vegetation was growing therefore this disturbance was considered as part of the 5-acre SMO limit. The site is in compliance at this time.

Continue to monitor this site when in the area.

Inspector's Signature *[Signature]*

LK:pb

File Name and Path

Date: January 19, 2007